E.M.S. 120 Plate transfer / fusing machine



This little magnetic tensfer / fusing machine allow to fuse jacket Parts and sportwears, it allow also to make transfer and sublimation. This machine doesn't need air comprimed.



The Control Unit

Respect of fusing parameters is the most important part of the process, EMS 120 fusing machine control panel includes:



- Set/Actual temperature
- On/Off button
- Pressure indicator
- Pressure regulator
- Fusing time in seconds
- Double safety starting button

Heating System

EMS 120 Series has an aluminium heating plate 20 mm tick with 3 snake heating element inside.

The heating Element

Nichel/Chrome

The Pressure System

Ems 120 has a magnetic pressure system. The pressure can reach 1 Kg. Sq/cm

E.M.S. 120 Technical Data

Model	Useful press area Mm (inch)	Working Plate	Air Pressure Volume Ø=8 mm	Electrical Volt/Hz/Kw	Dimensions: LxWxH Mm (inch)	Weight Kg (lb)	Air Consumption l/min
EMS 120	1200X550 (47X21)	1	0	2X 220/50-60/3 Kw/h 2	1200X900X550 (47x35x21)	200 (440)	0